

LITTLE FALLS, MN
HUB
LITTLE FALLS HUB

9364 7' X 3-2" DUCTS

Place conduit
from pole to pole
Pull new .625 through
& splice immediately after
placement. notify affected
customers * High Priority *

.625 uG
Conduit

1496-1259

30LL0411			
FNB99DJxx6x6x1			
13	16	25	
49	43	34	
1	12	0	2.0
21	21	29	25
8	3	B	T
60.00	1.86		
J / S	3		

STC2LTF136

County Rd 259

153RD ST

TAMMY AVE

MARY LN

DRIVEWAY

EXISTING
B
5.84
(15)AMP
STAND-BY

EXISTING
POLL
TRANSFORMER

15745

1060 30LL0416			
FNB99DJxx6x6x1			
19	14	24	
49	43	34	
7	5	0	2
21	21	31	28
6	2	B	I
53.41	1.02		
E / J	5		

NODE 30LL04
NODE 30LL03

22 / 13 / 18
316