




GasService Site Check
401 South Hawthorne St
Status: Ready

Inspection Date:	09/16/2026
Inspector:	John Wold
Service Center:	St. Cloud
Hours/Mileage:	0.75 hrs. / 12 mi.
Designer:	Shane Peterson
Work Order #:	116424864

Service Type:	Residential	Service Location:	Long Side
Job Site Conditions:	n_a	Length of Service line from Property Line to Gas Meter:	45

Bore Needed:	Yes	Traffic Control Needed:	Yes
Utilities needing to be Spotted along Bore Route:	Yes		
Route Obstructions:	No		
Locates Marked:	No	Route Flagged:	Yes
Gas Meter Location Marked:	Yes	Sewer Cleared:	N/A
Will the gas meter need to be vented?	No		
Developer Name:	Homeowner	Date of Site Readiness:	
Made contact with builder:	No		
Length of Service Lines:	105	Is site within 6" of Final Grade:	Yes
Designer Comment:			



Address



Gas meter location



Gas service route flagged