

GAS ASBU" T

Address: 21 1st St. Swanville

Property:

WO: 13 SC-SW-81-SWS-5066-


132523167

9-11-13

Personage

White Flag

Flagged 9/16 C.S.



Remarks:

4' Bore under Side Walk
1" PE CESA STD 7513

Material List	Lot #	Qty
Pipe 5/8" or 1"		73
Tee 2x5/8 or 2x1		
Tee 4x5/8 or 4x1		
Tee 6x5/8 or 6x1		
EFV 5/8 or 1"		1
2 5, 10 or 12 # Meter Bar		1
Cplg 5/8 or 1 or 2"	Bracket - post Foundtn.	1
Split Bolt 1	Riser 5/8 or 1" 1	
5/8 or 1" ELL	Cap 5/8 or 1"	
PE Tee 5/8 or 1" 1	PE Reducer 5/8x1" 1	
Carsonite	Anode 3#	
# of Heaters	Restoration Y N	

Meter			
Locked ☐	Unlocked ☒		
Size 250	Location West		
MFG Sensus	Reading 0000		
New Meter # 18171122			
Reg. Type/Press. 2#	5#	10#	12#
Old Meter#			
Old Meter Reading:			
Does Winter Construction Apply?	Y	N	

Condition of Existing Pipe			
Outside	Inside	Coating	
Good ☐	☐	☐	
Fair ☐	☐	☐	
Bad ☐	☐	☐	
Anode #	MV Reading		

Existing Main			
Size 2	Pressure 100	Type/Mfr Dura-Line	
Lot # See Remarks	Cover 30	Location -	
New Service / Main			
Size 1"	Lot # See Remark 5		
Poly Mfr Dura-Line	Nature of Soil Sandy-Rocky		
Tap Size FE	Cover 30	Completion Date 9-16-13	
Foreman ID SS78	Welder/Fuser ID 7945		
Pressure Test			
Test With: Air X Nitrogen	Duration 30	Emp ID 7945	
Date Tested 9-16-13	PSI 152	Soap Test Final Tie-in? Y X N	
Filled out by Mapping Dept.			
Mapped in System Maps	Date		
Mapped in GIS	Date		
Entry Person	Date		
GSOC Polygon Available	Yes	No	

Description	Install Footage
Directional Bore	
Pneumatic Bore	4
Backhoe	
Inserting	
Trench	
Plow	69
Hand Digging	
Splitting	
Joint Trench	
Gopher Pipe	
Cust. Perf. Loc.	