



Replace bad pole in same location as existing.
Approx. 1700 ft north of 160th st & 45 ft east of CL on CR 11.
Minimum clearance over CR 11 = 22 ft.
Pole near driveway entrance at 16324 Bison Rd.